

Kodak i1800 Series Scanners ISIS Driver Update Release Notes

ISIS Driver Version eki1860_2.0.10807.28001 Summary

Date: July 28, 2008

New Features from version 2.0.10801.24001:

1. (none)

Improvements from version 2.0.10801.24001:

1. PR#11772-[Non-English Interface Only] Can not configure Front/Rear imaging individually.
2. ISIS#2825/PR#12024-Retention of Image address level 1 values between enables is off by -1.
3. ISIS#2663-Incorrect Scan Area. Wrong Image's Width and Length values were being saved before synchronizing resolutions.